5. LEASE

NOO-C-14-20-7473

UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	Navado
	Nava Jo
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	<u> </u>
reservoir, ose roins 3-352-0 for soon proposess,	8. FARM OR LEASE NAME
1. oil gas uvell other	Charley
	9. WELL NO.
2. NAME OF OPERATOR	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Merrion Oil & Gas Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Gallegos Gallup Extension
P. O. BOx 1017, Farmington, New Mexico 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA GEBRA
below.)	Sec. 21, T27N; R13W
AT SURFACE: 646' FSL and 1850' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	San Juan The New Mexico
Salle	14. API NO. 목표권을 된 스트립스
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW_DF, KDB, AND WD)
DECUCOT CON APPROVAL TO CURRENT DEPORT OF	6055' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	हिं <mark>स्के अ -</mark> १०००
FRACTURE TREAT	중 ³ 링크 - 구 [4]
SHOOT OR ACIDIZE TO RETORING TO THE)
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING MAY 1 6 1984	change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES BURRAU OF LAND MANAGEMENT FARMING OF SEACHINGS ARE	% ಕ್ರಾಪ್ತಿಕ ಪ್ರಾತ್ಯ ಕ್ರಾಪ್ತಿಕ ಪ್ರತ್ಯ ಪ್ರತ್ಯ ಪ್ರತ್ಯ ಪ್ರತ್ಯ ಪ್ರಾಪ್ತಿಕೆ ಪ್ರಾಪ್ತಿಕೆ ಪ್ರಾಪ್ತಿಕೆ ಪ್ರತ್ಯ ಪ್ರತ
(other) Spud, Surface Casing	·
(00.0)	그 / 그 그 그 기 설립 호텔 그 6 기 향속 없지 다.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent.)	irectionally drilled, give subsurface locations and
Spud - 5/13/84	
Set 9=5/9"	TO With 175 cm of by case (250 5
gu ft) coment	KB with 175 sx 64 ass b (360.5
Set 8-5/8", J-55, 24 #/ft. surface casing @ 222'cu. ft.) cement. Circulated 3 Bbls to surface.	and the second s
Tested to 600 PSI for 30 minutes. Held OK.	
	୍ୟୁ କୁନ୍ଦିର କୁନ୍ଦି କୁନ୍ଦି ପ୍ରତି
DEGE 1000	
n English with a salet of soleton	
	Lastin at Italia
	2 1984 - 종류 중국 교육 교육 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
MATZ	TALLER BY SHEET
OIL CO	M. Div. Edge an ange
Subsurface Safety Valve: Manua and Type	· ~ 3
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the firegoing is true and correct	
SIGNED TITLE President	DATE5/14/84
(This space for Federal or State offi	ice use) //UCEFTED TOX-RELEGIED
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	- MAY 2 1-498 E = +
	PARIMINGTON NESCONDE AIREA
	By 25 - Snm -
	NY 2