
## BAYLESS DRILLING COMPANY

Marshall #3-E SW/4 Section 1-T27N-R9W San Juan County, New Mexico

## SLOPE TEST

Depth	Hole Deviation
296	1/4°
771	1/2°
1352	3/4°
1874	3/4°
2918	. 1/4°
4208	1/2°
4731	1/2°
5279	3/4°
5463	1°
6258	1°



	MAR 25 1985
State of New Mexico )	ON CON. DIV
) ss County of San Juan )	213 <sub>1</sub> , 3
I, Price M. Bayless and state that the above and for figures are true and correct to belief.	_, being first duly sworn, depose regoing depth and hole deviation the best of my information and
Subscribed and sworn before me t	this 12 day of March , 19 85.
	Hayle Julde NOTAR
My Commission Evnires	" 0 B 1 1 C

08/23/86

