Bunny #2-E SW/4 of Section 11-T27N-R9W San Juan County, New Mexico

SLOPE TEST

Depth	Hole Deviation
300 825 1378 1885 2576 3071 3592 3831 4540 5186 5766 5977	1/4° 1/4° 1/2° 3/4° 3/4° 3/4° 1° 1° 1° 1° 1° 1° 1° 1°
6795 (TD) State of New Mexico)) ss County of San Juan)	1 1/2° MAR 25 1985 CAN DAY

I, Price M. Bayless, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 12 day of March 1985.

Sayle Luder of (LE FI),
Notary Public NOTAR, 2

My Commission Expires

08/23/86