						s orga approved			
Form 3160-5 (November 1983) (Formerly 9-331)	DEPART	UNITED STAT		SUBMIT IN TRI (Other instruction verse side)	PLICATE*	Expires Augus 5 LEASE DESIGNATION	No. 1004-0135 t 31, 1985		
		U OF LAND MAN				SF 077972			
(Do not use this	IDRY NOT	ICES AND RE	PORTS OF		voir.	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME		
OIL GAS WELL OTHER						7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR						8. FARM OR LEASE NAME			
3, ADDRESS OF OPERATO	Union Texas Petroleum Corporation						Richardson		
P. O. Box 1290	P. O. Box 1290, Farmington, New Mexico 87499						5E		
See also space 17 be	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)						10. FIELD AND POOL, OR WILDCAT		
At Burrace	See also space 17 below.) At surface 845' FSL; 987' FEL PECEIVED						Basin Dakota 11. sec., T., R., M., OR BLK. AND		
				JAN 101995		SURVEY OR AREA			
14. PERMIT NO.	BUREAU OF LAND MANAGEMEN 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. PERMIT NO. 15. ELEVATIONS (Show whether of particle) PERCURY AREA 1. ELEVATIONS (Show whether of particle				GEMENT	Sec. 10, T27N-			
		5990' G			and the comments	San Juan	New Mexico		
16.	Check A	opropriate Box To	Indicate Nat	ure of Notice Re	mort or O				
	NOTICE OF INTER		1	ore or reduce, req	•	BNT REPORT OF:			
TEST WATER SHUT-		PULL OR ALTER CASING		W. 635 6776 636	<u></u>	1			
PRACTURE TREAT	· —	MULTIPLE COMPLETE		WATER SHUT-OFF FRACTURE TREATS	ļ 	REPAIRING ALTERING O	11		
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACI		ABANDONME	<u> </u>		
REPAIR WELL		CHANGE PLANS		(Other) Run		Production Cas	·		
(Other)				(Note: Ren	ort results	of multiple completion tion Report and Log fo	on Well		
1. Drilled 7-7/8	hole to	total depth o	DBUFIACE IOCALION	letails, and give perti	nent dates, true vertical	including estimated data depths for all marker			
2. Ran DIL and Cl 3. Ran 168 jts., 4. Cemented stag	4-1/2", 1	0.5#, H-40 ca	sing and POZ with	set at 6274'. 8% gel and 1	DV to O# gils	ol at 2904' onite/sk. Tai	il in		
with 100 sx 5 surface between	0/50 POZ w	ith 2% gel, o	.6% FLA a	nd 10# salt/s					
Cemented stage with 100 sxs	e two with Class B wi	1300 sxs 65/	35 POZ wi	th 6% gel and					
3:45 PM 12/30 5. NDBOP, set ca	sing slips		casing.						
6. Release rig 5					OIL C	IAN 3 1 1985 CON. DIV.			

8. I hereby certify that the foregoing is true and correct SIGNED Stations	TITLE Petroleum Engineer	DATE1/4/85
(This space for Federal or State office use) APPROVED BY	TITLE	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:		JAN 2 8 1985
* Se	ee Inst MANTO Reverse Side	FARIMINATOR RESCURCE AREA