

MERRION OIL & GAS CORPORATION

Charley J. No. 1  
990' FSL and 990' FWL  
Sec. 21, T247N, R13W  
San Juan Co., New Mexico

SLOPE TESTS


<u>Depth</u>	<u>Hole Deviation</u>
224	3/4
722	1
1258	3/4
1758	1
2259	1
3070	1
3599	1
4597	1
5370	3/4

RECEIVED  
JAN 27 1986  
OIL CON. DIV.  
DIST. 3

State of New Mexico )  
County of San Juan ) ss

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 24th day of January, 1986.

  
\_\_\_\_\_  
Notary Public

My Commission Expires 12/11/89