Feb. 1	m 9-831a Feb. 1951)				
	 	ļ			
ļ					
		Ì	:		
j					
1		i	1		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office		ta Pe	3
Lease No	3	03003	<u>3</u> _A
Unit			

SUNDRY NOTICES AN	D REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL.	SUPPLEMENTARY WELL HISTORY.
(INDICATE ABOVE BY CHECK MARK NAT	December: 20 , 19 56
· · · · · · · · · · · · · · · · · · ·	line and 15.00 ft. from $\begin{bmatrix} E \\ W \end{bmatrix}$ line of sec. 25
Sp. 31 270 (County or St. (County or	W - W
The elevation of the derrick floor above sea level	/RITI/EXX
(State names of and expected depths to objective sands; show sizes, ing points, and all other	weights, and lengths of proposed casing in ficate mudding jobs, competrimportent proposed work) d adandon as follows: DIST, 3
To rum 2" to bottom and circup into casing approx 200'. To pump cement form casing a into water sand. To pump cemproduction string and surface cement plug at surface clean up location.	To let set and check for fillup. Ind squeeze through split or hole sent down annular space between se of casing and squeeze. of casing, place marker and
enter the hole from a water	in the 7" casing, causing water to sand about 500 deep. This casing practicable to repair.
Company John A. Funn	
Address Box 1208	Original Signed
Formington, New Mexico.	By John A. Egan
	Title Operator
U. S. GOVERNMENT	PRINTING OFFICE 16-8487-5