DEVIATION REPORT

Name of Company

Burlington Resources Oil & Gas Company Lease Name and Number

HUERFANO UNIT #77R

Pool and Formation

Fulcher Kutz Pictured Cliffs

 Unit Letter

-990 FSL 1,595 FEL

-

P. O. Box 4289, Farmington. NM 87499

Sec. Twn.

027N

Rge. 010W

County

SAN JUAN

Address

Depth (Ft.)	Deviation (Degrees)
10	.00
139	.25
486	.25
1,012	.25
1,512	.25
1,873	.75

Air Hammer Used? YES NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for BURLINGTON RESOURCES OIL AND GAS CO., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 3rd day of June, 1999

Notary Public in and for San Juan County, New Mexico My commission expires August 17, 2000 Leslo 11 Inte

JUL - 1 1399