

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Juan  
Lease No. 52-065454  
Unit San Juan

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED  
NOV 27 1961

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

November 21, 1961

Well No. 1 is located 110 ft. from N line and 100 ft. from E line of sec. 3

Section 3 (1/4 Sec. and Sec. No.) T-2N (Twp.) R-10E (Range) Meridian (Meridian)


San Juan (Field) San Juan (County or Subdivision) San Juan (State or Territory)

The elevation of the derrick floor above sea level is 5950 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well was spudded 11/21/61  
Set 10 jts., 8 5/8" casing, landed at 317' with 225 ex. cm.  
Packed casing with 500# pressure for 30 minutes. No leaks.  
Drilled cement 11/22/61  
Tested with 500# pressure for 30 minutes  
No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil & Gas Corp.

Address Drawer # 570

Farmington, N.M.

By ORIGINAL SIGNED BY JOE C. SALMON

Joe C. Salmon

Title District Superintendent