

A 4x4 grid with a dot in the bottom-right cell.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. 075634

Unit 1: Introduction to the course and the importance of the study of the history of the United States.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 19 _____, 1919

Well No. 11 is located 100 ft. from [S] line and 1250 ft. from [E] line of sec. 11

11 Sec. and Sec. No. (Twp.) (Range) (Meridian)

State of Ohio (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 512 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 1935 Run logs: Top of Fractured Cliffs - 1870'
Perforated 1835-1925 with 4 shots per foot
Set oil joints, 1923' of 1 1/2" casing at 1935' with 100 sacks cement
Top of Cement - 1950'
Swelled hole dry
Tested 2 hours with 500# pressure
Pipe Okay.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Artes Oil and Gas Company

Address Box 124

Marinton, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By _____

Title Deputy Superintendent **Joe T. Salvo**