

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 3360, Casper, Wyoming 82602

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1100' FSL & 1520' FEL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Cementing Information

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☐

5. LEASE

NM 048569

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

--

7. UNIT AGREEMENT NAME

--

8. FARM OR LEASE NAME

Mexico Federal "S"

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Bloomfield Chacra

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9-T28N-R10W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

--

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5835' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8 5/8" casing was set with 275 sx of cement. Circulated out 10 sx of cement.

4 1/2" casing was set with 370 sx of cement. Cement top estimated at 250'.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles E. Mowry TITLE Area Engineer DATE 6-11-81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NMCCC

FOR RECORD

*See Instructions on Reverse Side

BY Dean Elliott



Getty Oil Company, P.O. Box 3360, Casper, Wyoming 82602

Central Exploration and Production Division

June 12, 1981

Mr. James F. Sims
District Oil and Gas Supervisor
U.S. Department of the Interior
Geological Survey
Drawer 600
Farmington, New Mexico 87401

Dear Mr. Sims:

Attached is a Sundry Notice reporting the cementing information which you requested in your letter dated May 20, 1981 in reference to our Mexico Federal "S" Well No. 1.

This well is currently shut in waiting on a completion unit. Therefore, we have not yet run a cement bond log and the cement top behind the 4 1/2" production casing is an estimated top. We would be happy to report the actual cement top as soon as the data is available to us.

Sincerely yours,

A handwritten signature in cursive script that reads 'Charles E. Mowry'.

C. E. Mowry
Area Engineer

SP/cs

