

L-9-99N-2W

30-039-26094

Cyclone Drilling

Mallon Oil Company
Survey Report
Jicarilla 29-02-09 No. 1

<u>Date</u>	<u>Footage</u>	<u>Degrees</u>
2-3-99	384'	$\frac{3}{4}$ degree
	559'	$\frac{3}{4}$ degree
2-4-99	1054'	$\frac{1}{2}$ degree
2-5-99	1614'	$\frac{3}{4}$ degree
	2107	$\frac{1}{2}$ degree
2-6-99	2665'	1 degree
	3123'	$\frac{3}{4}$ degree
2-7-99	3616'	$\frac{3}{4}$ degree
2-8-99	3870'	$\frac{3}{4}$ degree

