

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe
Lease No. 076903
Unit _____

A. P. Greer
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Payne

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 19 52

Well No. 7 is located 990 ft. from S line and 990 ft. from W line of sec. 35

SW/4 Sec. 35 28N 12W NMPH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

West Kuts San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5917 ft. (Ground)
5925 K 19

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7/26/52

TD. 78'

Pressured up on surface casing to 500#.
No pressure drop in thirty (30) minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Martin
Address 315 1/2 West Main St.
Farmington, N. M.

By Albert R. Greer
Albert R. Greer.
Title Field Sup't.

OIL CONSERVATION COMMISSION
AZTEC DISTRICT OFFICE

No. Copies Received 2

DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe	1	
Proration Office		
State Land Office		
U. S. G. S.		
Transporter		
File	1	✓