

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078903

Unit Payne

SUNDRY NOTICES AND REPORTS ON WELLS

|                                                |                                            |                                     |
|------------------------------------------------|--------------------------------------------|-------------------------------------|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |                                     |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       |                                     |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR  |                                     |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           |                                     |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 |                                     |
| NOTICE OF INTENTION TO ABANDON WELL            |                                            |                                     |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 19 52

Well No. 5 is located 1650 ft. from [N] line and 1650 ft. from [E] line of sec. 35


NE/4, Sec. 35 28N 12W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
West Kuts San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5253 ft. (Ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/14/52 TD 88'.  
Pressured up on surface casing to 500'. No pressure drop in 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Montin

Address 315 1/2 West Main St.

Farmington, N. M.

By Albert R. Greer

Title Field Sup't.

O L CONSERVATION COMMISSION

AZTEC DISTRICT OFFICE

No. Copies Received

DISTRIBUTION

|                   | NO.<br>FURNISHED |   |
|-------------------|------------------|---|
| Operator          |                  |   |
| Santa Fe          | 1                |   |
| Flotation Office  |                  |   |
| State Land Office |                  |   |
| U. S. G. G.       |                  |   |
| Transporter       |                  |   |
| File              | 1                | ✓ |