

#### (SUBMIT IN TRIPLICATE)

# UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	079346-A
Unit	I-Sec. 844
Gallegos	Canyon Unit

#### SUNDRY NOTICES AND REPORTS ON WELLS

<u></u>			<del></del>
NOTICE OF INTENTION TO DRILL	SUBSEQUENT	T REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT	T REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SH	IUT-OFFSUBSEQUENT	T REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR R	EPAIR WELL SUBSEQUEN	T REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIE	NZESUBSEQUENT	T REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER	CASINGSUPPLEMEN	TARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
(INDICATE ABO	OVE BY CHECK MARK NATURE OF REPOR	RT, NOTICE, OR OTHER DATA)	
		May 11	, 19 <u>53</u>
Well No. 41 is located	1 990 ft. from $\binom{N}{S}$ line as	nd990 ft. from $\left  egin{array}{c} \mathrm{E} \ \mathrm{W} \end{array}  ight $ line of	sec32
NE/4 NE/4 Sec. 32 (14 Sec. and Sec. No.)	28N 12W (Twp.) (Range)	N. M. P. M. (Meridian)	
		New Mexico	_
(Field)	(County or Subdivision)	(State or Territory)	
Pictured Cliffs Sand Surface Casing: 901 Production Casing: 1	test. Estimated depth of 9-5/8" OD 32# cemes 400° of 7" OD 20#, cention is indicated, the	ingths of proposed casings; indicate muddice reposed work)  h 1500!.  nted to surface.  mented with 100 sacks.	RECEIVED
I understand that this plan of work mus  Company BENSON-MONTIN	t receive approval in writing by the Ge	sological Survey before operations may be	commenced.
Address 315 West Main	1		n 100,
Farmington, Ne	w Mexico	By Cellus	( A Sie
		Title Field Superints	andent

Carried Control

#### 

## TO STANTES OF LEVEL AND A TAKEN STATE OF THE STATE OF THE

and the state of t

### 

A CONTROL OF THE PROPERTY OF T

to the control of the

in the second of the second of



um in the later to the control of th