


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, N. Mexico

Lease No. NM 020501

Unit \_\_\_\_\_



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Completion Date <u>                    </u> <u>XX</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 3, 1960

Ohio Government

Well No. 2-25 is located 1376 ft. from {N} line and 170 ft. from {E} line of sec. 26

NE 1/4 Sec. 26  
(1/4 Sec. and Sec. No.)

T2S  
(Twp.)

R10E  
(Range)

(Meridian)

Kuts Canyon  
(Field)

SAN JUAN COUNTY,  
(County or Subdivision)

NEW MEXICO  
(State or Territory)


The elevation of the ~~derick floor~~ derick floor above sea level is 5509.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Initial deliverability test November 23, 1960: Flow at end of 3 hours on 3/4" choke 9,031 MCFPD, calculated absolute open flow 23,001 MCFPD. Flowing pressure - tubing 724 psi, casing 1761 psi. Seven day shut-in pressures - tubing 1884#, casing 2090#.

Well completed at total depth 6249', plug back 6205'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Ohio Oil Company

Address P. O. Box 120

Casper, Wyoming

By H. J. Brunt

Title Division Production Superintendent


1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes the need for transparency and accountability in financial reporting.

2. The second part of the document outlines the various methods and techniques used to collect and analyze data. It includes a detailed description of the experimental procedures and the statistical analysis performed.

3. The third part of the document presents the results of the study. It includes a series of tables and graphs that illustrate the findings of the research. The data shows a clear trend in the relationship between the variables studied.

4. The fourth part of the document discusses the implications of the findings and provides recommendations for future research. It suggests that further studies should be conducted to explore the underlying mechanisms of the observed phenomena.

5. The fifth part of the document concludes the report and summarizes the key points. It reiterates the importance of the research and the need for continued efforts in this field.



1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes the need for transparency and accountability in financial reporting.