

	X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF-080844
Unit T. L. Rhodes

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>8-5/8"</u>	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

T. L. Rhodes

Farmington, New Mexico May 21, 1963

Well No. 1 is located 2000 ft. from N line and 1900 ft. from W line of sec. 30

S. 1/4 NW 1/4 Section 30 T-28N R-11E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


Simpson Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5950' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was spudded May 2, 1963 and drilled to a depth of 217'. 8-5/8" casing was set at that depth with 130 sacks cement containing 2% calcium chloride. Cement circulated to surface. After waiting on cement tested casing to 1000 psi. Test ok. Reduced hole to 7-7/8" and resumed drilling.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address P. O. Box 480

Farmington, New Mexico

Attn: L. O. Speer, Jr.

By ORIGINAL SIGNED BY
E. H. HOLLINGSWORTH

Title Petroleum Engineer