

30-045-07332

Budget Bureau 42-R358.2
Approval expires 12-31-52.X
COPY TO O.C.C.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 077946
Unit I-Sec, 644
Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

JUN 30 1953

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	☐
NOTICE OF INTENTION TO CHANGE PLANS	☐	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	☐
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	☐	SUBSEQUENT REPORT OF ALTERING CASING	☐
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	☐	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	☐
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	☐	SUBSEQUENT REPORT OF ABANDONMENT	☐
NOTICE OF INTENTION TO PULL OR ALTER CASING	☐	SUPPLEMENTARY WELL HISTORY	☐
NOTICE OF INTENTION TO ABANDON WELL	☐		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 29, 19 53

Well No. 38 is located 1440 ft. from N line and 735 ft. from E line of sec. 24SE/4, NE/4, Sec. 24
(1/4 Sec. and Sec. No.)28N
(Twp.)19W
(Range)N.M.P.M.
(Meridian)West Gate
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (Not available. Will furnish later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


Pictured Cliffs Sand test. Estimated depth 1400'.

Surface Casing: 90' of 8-5/8" cemented to surface.

Production Casing: 1300' of 5-1/2" cemented with 100 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMAN-MONTENAddress 315 1/2 West MainFarmington, New MexicoBy Albert R. GreenTitle Field Superintendent

Land Office _____
License No. _____
Unit _____
City _____

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK INTENT OF REPORT, NOTICE, OR OTHER DATA)

Well No. _____

Well No. _____ is located _____ from _____ line of sec. _____

_____ (Field)
_____ (State or Territory)
_____ (County)
_____ (Township)
_____ (Range and Sec. No.)

The elevation of the derrick floor above sea level is _____

DETAILS OF WORK


(State names of and quantities of materials used, flow meter readings and test results of proposed casing, and all other pertinent proposed work)

I understand that this plan of work must receive approval of the Geological Survey before operations may be commenced.

Company _____

Address _____

COMPANY- Benson Montin
LEASE Gallegos Canyon Unit-Well No. 38
SECTION 24 T28N R13W N.M.P.M.
LOCATION - 1660 from north line
735 from east line
San Juan County New Mex



This is to certify that the above
plat was prepared from field notes of
actual surveys made by me & are true
and correct to the best of my knowledge
& belief.

Robert L. Maddox Jr.
Robert L. Maddox Jr.
Reg. Professional Engineer
& Land Surveyor
N.M. Reg. No. 1426

Surveyed 3-8-53