

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 678828
Unit I-Sec. 844
Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 3, 1954

Well No. 68 is located 1750 ft. from N line and 1750 ft. from E line of sec. 14

SW/4 NE/4 Sec. 14 (1/4 Sec. and Sec. No.) 28E (Twp.) 12W (Range) N.M.T.M. (Meridian)
West Kutz (Exx) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (Not available - will furnish later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs Sand Test - Estimated Depth 1650'.

Surface Casing: 80' of 10-3/4" OD 32.75* cemented with 80 sacks.
Production Casing: Approximately 1600' of 5-1/2" OD 14* J-55 cemented with 100 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN

Address 315 1/2 West Main

Farmington, New Mexico

By [Signature]

Title Field Superintendent

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL					
NOTICE OF INTENTION TO PULL OR ALTER CASING					
NOTICE OF INTENTION TO SHOOT OR ACIDIZE					
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL					
NOTICE OF INTENTION TO TEST WATER SHUT-OFF					
NOTICE OF INTENTION TO CHANGE PLANS					
NOTICE OF INTENTION TO DRILL					
SUPPLEMENTARY WELL HISTORY					
SUBSEQUENT REPORT OF ABANDONMENT					
SUBSEQUENT REPORT OF REDRILLING OR REPAIR					
SUBSEQUENT REPORT OF ALTERING CASING					
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING					
SUBSEQUENT REPORT OF WATER SHUT-OFF					

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE OR OTHER DATA)

10

Well No. _____ is located _____ ft from _____ N _____ E _____ ft from _____ W _____ line of sec. _____

(M Sec and Sec No.) (Twp.) (Range) (Meridian)
(Yield) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudlogging jobs, sample logs, points, and all other important proposed work)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company _____

Address _____

By _____

Title _____


Company..... BENSON-MCATIN

Lease Gallegos Canyon Unit Well No. 68

Sec. 14, T. 28N, R. 12W

Location 1750 feet from north line; 1750 feet
from east line.

RECORDED
MAY 4 1954
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.



Scale—4 inches equal 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Stephen H. Kinney

Seal:

Registered Professional
Engineer and Land Surveyor.

Surveyed May 1, 19 54

MAY 11 1954
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.