



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 3F-077968
Unit C. J. Holder

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C. J. Holder

Farmington, New Mexico October 10, 1961

Well No. 3 is located 680 ft. from Dr line and 610 ft. from E line of sec. 8

SE/4 SE/4 of Section 8

T-28-N

R-13-W

N.M.P.M.

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Cha Cha Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6034 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Moved in pulling unit, pulled tubing and checked top sand at 5770'.
2. Bridge plug set at 5705', tested with 3000 psi ok, and perforated main Gallup pay with 6 shots per foot 5680-5688'.
3. Sand oil fracked with 3000 gallons oil spearhead and 23,500 gallons oil containing 50 pounds Adomite Mark II per 1000 gallons oil and 15,000 pounds 20-40 sand and 5000 pounds 10-20 sand.
4. Cleaned out, retrieved bridge plug and tested.
5. Completed as Cha Cha Gallup field Development well September 6, 1961. Potential test September 6, 1961, flowed 108 barrels of oil in 24 hours on 32/64" choke with tubing pressure flowing 125 psi and casing pressure flowing 300 psi.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address P. O. Box 480

Farmington, New Mexico

Attn: L. O. Speer, Jr.

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

By

Title Senior Petroleum Engineer