


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **SP-077968**
Unit **Southeast Cha Cha Unit**



RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS - 1962

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Southeast Cha Cha Unit

Farmington, New Mexico June 29, 1962


Well No. **9** is located **600** ft. from **S** line and **1880** ft. from **E** line of sec. **9**
SE 1/4 SW 1/4 Section 9 **T-28-N** **R-13-W** **N.M.P.M.**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Cha Cha Gallup **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6028** ft. (RDB)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This is to advise of redesignation of C. J. Holder Well No. 6 to Southeast Cha Cha Unit No. 9 with approval of Southeast Cha Cha Unit effective 7:00 A.M. July 1, 1962.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pan American Petroleum Corporation**

Address **Box 480**

Farmington, New Mexico

Attn: **L. O. Spear, Jr.**

ORIGINAL SIGNED BY
L. R. Turner

By _____

Title **Administrative Clerk**