

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

I-149-Ind-8470

6. If Indian, Allottee or Tribe Name

Navajo Tribe

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gallegos Canyon Unit #193

9. API Well No.

30-045-11570

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan, NM

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Amoco Production Company Attn: John Hampton

3. Address and Telephone No.

P.O. Box 800 Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1525' FNL, 910' FWL Sec. 30, T28N-R12W Unit "E"

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Bradenhead Repair
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Please see attachment for procedures.

RECEIVED
APR 1 1992
OIL COLL. DIV.
DIST.

ACCEPTED FOR RECORD
APR 1 1992
FARMINGTON RESOURCE AREA
BY [Signature]

RECEIVED
APR 1 1992
OIL COLL. DIV.
DIST.

If you have any questions please contact Ed Hadlock @ (303) 830-4982.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Sr. Staff Admin. Supv.

Date 3/31/92

(This space for Federal or State office use)

Approved by _____

Title _____

Gallegos Canyon Unit 193

2/21/92 - 2/26/92

MIRUSU, NDWH, NUBOP, TIH tagged Fill @ 6205' (21' fill) - tallied and TOH with Saw tooth, 1jt, SN, 197 jts,- TIH with bit and scraper W/STD valve in place to 6205', press. test TBG to 2000psi. RIH with fishing tool to retrieve STD. valve unable to latch valve- pulled 2 stds. TOH W/bit and scraper. TIH with RBP and set @ 6024', press test to 1000 psi. Held ok. TOH W/ RET Head- RU WLE. and run CBL, CCL, GR, from 3200' to surf. Fair cmt to 500'- no definite cmt top. Press up W/water to 800psi.- press bled off 500psi. in 2min. holding 300psi. Took very little water to press. up. TIH W/ RET Head for RBP set @ 6024', latched RBP and TOH. TIH with 1/2 mule shoe, 1 jt, SN, 197 jts 2.375" tbg, Landed TBG @ 6158'. NDBOP, NUWH. Well ready to be put on Prod.