



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 13, 1993

Ms. Judy McLemore
Conoco, Inc.
10 Desta Drive, Suite 100W
Midland, TX 79705-4500

RE: Illegal Pits in Northwest New Mexico
Krause Federal WN #2E, P-28-28N-11W

Dear Ms. McLemore:

Field inspections conducted on December 13, 1993 by Charles Gholson revealed that the above mentioned pit has been netted as per requested and no longer requires a C-134.

If you have any questions please feel free to call me at 505-334-6178.

Yours truly,

Dianna K. Fairhurst

Dianna K. Fairhurst
Deputy Oil & Gas Inspector

xc: Don Ellsworth - BLM Farmington
C-134 Correspondence
Well File

Submit 4 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-134
Aug. 1, 1989

DISTRICT I
P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88211-0719

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Permit No. _____
(For Division Use Only)

APPLICATION FOR EXCEPTION TO DIVISION ORDER R-8952
FOR PROTECTION OF MIGRATORY BIRDS Rule 8(b), Rule 105(b), Rule 312(h), Rule 313, or Rule 711(I)

Operator Name: ARCO Oil and Gas Company, Div. of Atlantic Richfield Co. CONOCO
Operator Address: 1816 E. Mojave, Farmington, New Mexico 87401. MIDLAND
Lease or Facility Name Krause Federal WN 2E Location P SEC 28, T-28N, R-11W
Size of pit or tank: 15 x 25 x 4 Ut. Ltr. Sec. Twp. Rge

Operator requests exception from the requirement to screen, net or cover the pit or tank at the above-described facility.

☒ The pit or tank is not hazardous to migratory waterfowl. Describe completely the reason pit is non-hazardous.
This is a gas well which produces less than 10 gallons of liquid
hydrocarbons per day.

1) If any oil or hydrocarbons should reach this facility give method and time required for removal:
The liquid hydrocarbon will be removed by vacuum truck within 1 (one)
business day of occurrence if equipment should malfunction.

2) If any oil or hydrocarbons reach the above-described facility the operator is required to notify the appropriate District Office of the OCD with 24 hours.

☒ Operator proposes the following alternate protective measures: No protection is deemed necessary.
0

RECEIVED
SEP 05 1989

OIL CON. DIV.

CERTIFICATION BY OPERATOR: I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature Dave Corzine Title Sr. Prod. Supv. Date 01-Sep-89
Printed Name Dave Corzine Telephone No. (505) 325-7527

FOR OIL CONSERVATION DIVISION USE

12/13/93 CG THE PIT IS NOW NETTED


Date Facility Inspected _____

Inspected by _____

Approved by _____

Title _____

Date _____



NOT APPROVED