

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ well ☒ other ☐

2. NAME OF OPERATOR

Southland Royalty Company

1111 113th St. S.W.

P.O. Drawer 570, Farmington, N.M. 87401

3. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 910' FNL & 1060' FEL

AT TOP PROD. INTERVAL:

1060' FEL

REQUEST FOR APPROVAL TO: _____ SUBSEQUENT REPORT OF: _____
TEST WELLS SHUT-OFF _____

4. DRILL OR ALTER CASING _____

MULTIPLE COMPLETE _____

CHANGE ZONES _____

5. PERFORATION _____

6. Perforation & Stimulation ☒

7. Production Tubing Report ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-17-80 Perforated the Dakota at 6210', 6217', 6294', 6302', 6310', 6316',
6353', 6376', 6375', 6383', 6391', 6399', 6407'.

Total of 13 holes.

11-18-80 Frac'd Dakota with 149,760 gals 30# gelled 1% KCl water and
105,108# of 20/40 sand.

AIR 25 BPM, ATP 2150 psi, ISIP 650 psi.

Landed 204 joints (6386') of 2-3/8", 4.70#, J-55 tubing at 6397'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE District Prod. Mgr. DATE November 19, 1980

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY

BW