HICKS ENCO, INC.

FARMINGTON, NEW MEXICO 87401

June 24, 1981

New Mexico Oil and Gas Conservation Commission 1000 Rio Braxos Road Aztec, New Mexico 87410

> RE: Southeast Cha Cha Unit Well #39 - Sec.7 - T28N, R13W San Juan County, New Mexico

Dear Sir:

This is to certify that the following straight hole surveys were taken while drilling the subject well as reported by the drilling contractor:

Depth	Deviation
310'	½ ⁰
1290'	3/40
2297'	10
3253'	1 3/4 ⁰
4720'	1 3/4 ⁰ 3/4 ⁰
5771'	3/40

Sincerely,

JDH/11

OIL CON. COM. DIST. 3

