UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Southeast cha Cha 8. FARM OR LEASE NAME
1. oil gas other 2. NAME OF OPERATOR Hicks Enco, Inc. 3. ADDRESS OF OPERATOR	9. WELL NO. 38 10. FIELD OR WILDCAT NAME Cha Cha Gallup
P.O. box 174, Farmington, N.M. 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 990' from West Line & 2100' from South AT SURFACE: Line AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T28N, R13W 12. COUNTY OR PARISH San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6048 Gr. 6061 KB
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE U. S. GEOLE	27 (NOTE: Report results of multiple completion or zone change on Form 9-330.)
17 DECORDE PROPOSED OF COMPLETED OPERATIONS (OF 1.)	4.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/3/81 - Cleaned well out to 5790'. Perforated 5694 - 5708 with 2 holes per foot. Acidized with 500 gal. 15% HCL acid. 4-4-81 Frac treated with 40,000# of sand in 40,000 gal. of 70 quality nitrogen foam. 4-6,7 & 8-81 Swab tested well and cleaned sand out of well. 5-11-81 - Set pumping unit and started producing.

Subsurface Safety Valve: Manu. and Type		ACCEPTED FOR RECORD			Ft.
18. I hereby certify that the foregoing is SIGNED Miles Miles		DATE .	JUN 2 5/22/81		
	(This space for Federal or State office use)	В		010111101	
APPROVED BY	TITLE	_ DATE			

NMOCC