	Francisco de la companya della companya della companya de la companya de la companya della compa
RELEIVA	g 96 Postal allo na, company by t
SUITED FOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill onto deep C Mplug back o a different reservoir. Use form 11–331–C for such proposal.)	7. UNIT AGREEMENT NAME Gallegos Canyon Unit 8. FARM OR LEASE N. 15
1. oil gas well other	9. WELL NO. 226E
2. NAME OF OPERATOR Amoco Procuction Company 3. ADDRESS OF OPERATOR 501 Airport Drive, Farmington, NM 87401	10. FIELD OR WILDCAT NAME Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 980' FNL × 1400' FWL AT TOP FROD, INTERVAL: Same	AREA NE/4, NM/4, Section 18 T28N, FIDW 12. COUNTY OR PARIS 13. STATE San Juan NA
AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 30-045-24-48 15. ELEVATIONS (SHOT: DF, KDB, AND WD) 5578 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is different and true vertical depths for all markers and zones pertinent	illectionally dillied. Kive appartiace locations and
Completion operation commenced on 12-5-81. Total the plug tack depth is 6100'. No perforations operations. Tripped in hole and checked for san Circulatec hole clean with 2% KCl water. Made of fluid. Rig up air compressors and circulate Circulatec hole clean with air: Landed 2-3/8" on 12-9-11.	or fracturing too' "lace during nd fill. Taged 65' of fill. 10 swab runs and recovered 80 bbls ed an additional L F' of sand.
Subsurface Safety Valve: Manu. and Type	S <u>(</u> (i) Ft.
SIGNED	IPVr. DATE DEU
(This space for Federal or State of	
APPROVED BY	DATE

4 1 1

*See Instructions on Reverse Side

NMOCC

hammed the second