Marray 2, But

DEC 3 0 1857

į

Meter Number:94692 DEPUTY OIL & CAUTHE MCTOscation Name: FULLERTON G.C. #1E

Location:TN-28 RG-13 SC-34 UL-P

2 - Federal

NMOCD Zone:OUTSIDE

Hazard Ranking Score:00

RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

10⁻⁹ to 10⁻¹³ cm/sec Sandstone 10⁻¹² to 10⁻¹⁶ cm/sec Shale 10⁻¹² to 10⁻¹⁵ cm/sec Clay

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.


Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM ELPASOFIELD SE

GENERAL	Meter: 94692 Location: FullerTon D.C. # 16 Operator #: D203 Operator Name: Dence P/L District: Angel Pen Coordinates: Letter: P Section 34 Township: 28 Range: 13 Or Latitude Longitude Pit Type: Dehydrator K Location Drip: Line Drip: Other: Site Assessment Date: Area: Run: Run:				
SITE ASSESSMENT	NMOCD Zone: Land Type: BLM ☒ (1) (From NMOCD State ☐ (2) Maps) Inside ☐ (1) Fee ☐ (3) Outside ☒ (2) Indian				
	Depth to Groundwater Less Than 50 Feet (20 points) ☐ (1) 50 Ft to 99 Ft (10 points) ☐ (2) Greater Than 100 Ft (0 points) ☒ (3)				
	Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)				
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points)				
	(Surface Water Body: Perennial Rivers,Major Wash,Streams,Creeks, Irrigation Canals,Ditches,Lakes,Ponds) Distance to Nearest Ephemeral Stream ☐ (1) < 100'(Navajo Pits Only) ☐ (2) > 100'				
	TOTAL HAZARD RANKING SCORE: POINTS				
RKS	Remarks:				
REMARKS					
1 22	the same of the sa				

U Z
~
2
A
V
≥
Ξ
2

Original Pit: a). Degrees from North 60° Footage from Wellhead 580



Remarks:

Well HeAd 13 580 OUT IN A Field ON

NAPI

Completed By:

____CU. Hick

Signature

7-11-94

Date

FIEI PIT REMEDIATION/CLOSUTE FORM

GENERAL	Meter: 94692 Location: <u>FallerTON</u> <u>W. C.</u> #1E Coordinates: Letter: Section <u>34</u> Township: <u>28</u> Range: <u>/3</u> Or Latitude Longitude Date Started: Area: <u>O/</u> Run: <u>33</u>
FIELD OBSERVATIONS	Sample Number(s): Feet Sample Depth: Feet Final PID Reading PID Reading Depth Feet Yes No Groundwater Encountered
CLOSURE	Remediation Method: Excavation
REMARKS	Pit Closure Date: Pit Closed By: E.N.G. Remarks :
	Signature of Specialist:



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab ID	
SAMPLE NUMBER:	CVH7	9451049	
MTR CODE SITE NAME:	94692	N/A	
SAMPLE DATE TIME (Hrs):	7-11-94	1453	
SAMPLED BY:	N/A		
DATE OF TPH EXT. ANAL.:	7/14/44	7/14/94	
DATE OF BTEX EXT. ANAL.:	NM	NIA	
TYPE DESCRIPTION:	V (-	Born Sand Chy	

REMARKS: Needs PID

RESULTS

PARAMETER	RESULT	UNITS	rs QUALIFIERS	QUALIFIERS		
			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	410	MG/KG			2.12	28
HEADSPACE PID	1020	PPM			. :	
PERCENT SOLIDS	90.0	%				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate	Recovery	was	at
Narrative:			

 \mathcal{N}	A	

% for this sample All QA/QC was acceptable.

Approved By:

DF = Dilution Factor Used

For Total

Date: 8/12/44

74/07/14 10:53

Sample identification 745649


Initial mass of sample; g 2.120

Volume of sample after extraction, ml 38.000

Petroleum hydrocarbons, ppm 409.900

Net absorbance of hydrocarbons (2930 cm-1) 2.057

(. .



1