## TABULATION OF DEVIATION TESTS

## AMOCO PRODUCTION COMPANY

DEPTH	DEVIATION
692 <b>'</b>	1/2°
941'	O°
1381'	1/2°
1883'	1°
2410'	3/4°
2938 <b>'</b>	3/4°
3436'	1/4°
3997'	1/2°
4388'	1°
4895 <b>'</b>	1°
5422'	1°
5931 <b>'</b>	3/4°
6362'	1°
6505'	1°



## AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION COMPANY'S Gallegos Canyon Unit No. 244E, Section 36, T28N, R12W San Juan County, New Mexico.