

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

Land Office Santa Pe





## **UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

(SUBMIT IN TRIPLICATE)

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	
(INDICATE ABOVE BY CHECK MAR	K NATURE OF REPORT, NOTICE, OR OTHER DATA)
	, 19_5
/ell No. 8-34 is located 1850 ft. from	$\begin{bmatrix} N \\ B \end{bmatrix}$ line and $\begin{bmatrix} B & B & B \\ B & B \end{bmatrix}$ line of sec. $\begin{bmatrix} B & B \\ B & B \end{bmatrix}$
E/A ME/A Sec. 34 29 Earth (Twp.)	
Lanco Mosa Yerde Rio (Field) (County	or Subdivision)  (State or Territory)
he elevation of the garries for above sea le	evel is _7166. ft.
DETA	ILS OF WORK
tate names of and expected depths to objective sands; show sing points, and all	zes, weights, and lengths of proposed casings; indicate mudding jobs, cemer other important proposed work)
predded 6-7-57. Set 207.12' of 10-	3/4" casing @ 218.62', comented w/200 sx
1/2% CaCl. Casing tested ok. Set 4303.49° of 7-5/8" casing 6 431	5.49°, commuted w/150 sx 8% gel and 50 sx 3
w/2\$ CaCl. Casing tested ok. Set 4303.49' of 7-5/8" casing 6 431 Casing tested ok.	
7/2% CaCl. Casing tested ok. Set 4303.49' of 7-5/8" casing 6 431 Casing tested ok. Set 2220.40' of 5-1/2" liner 8 6440	', Burns Liner Hanger & 4220', commuted v/2
Set 4303.49° of 7-5/8" casing 6 431 casing tested ok.  Set 2220.40° of 5-1/2" liner 6 6440 regular. Tested w/3000f, hald ok.	5.49', comented v/150 ax 8% gel and 50 ax 1 ', Burns Limer Hanger & 1220', comented v/2  Note that the second of t
Company	n writing by the Geological Survey before operations may be distinguished.
Set 4303.49° of 7-5/8" casing 6 431 casing tested ok.  Set 2220.40° of 5-1/2" liner @ 6440 regular. Tested w/3000f, hald ok.  I understand that this plan of work must receive approval i	n writing by the Geological Survey before operations may be ammenced.
Jet 1303.19' of 7-5/8" casing # 131 casing tested ok.  Set 2220.10' of 5-1/2" liner # 6410 regular. Tested w/3000f, hald ok.  I understand that this plan of work must receive approval is company PACIFIC ECRIBEST PI	n writing by the Geological Survey before operations may in the Corporation

Millian)

•