

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

Santa Fe, NM 87505

FEB 19 1998

**OIL CON. DIV.**

**DIST. 3**

WELL API NO.	30-039-07616
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-289-67056
7. Lease Name or Unit Agreement Name	009256 San Juan 29-5 Unit
8. Well No.	SJ 29-5 Unit #10
9. Pool name or Wildcat	Blanco Mesaverde 72319
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR LOG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER ☐ 017654

2. Name of Operator  
Phillips Petroleum Company

3. Address of Operator  
5525 Highway 64, NBU 3004, Farmington NM 87401

4. Well Location  
Unit Letter L : 1650 Feet From The South Line and 990 Feet From The West Line

Section 16 Township 29N Range 5W NMPM Rio Arriba County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Remove packer & sliding sleeve ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In February 1997 the Lewis Shale pay was added to the existing Mesaverde interval. A packer and sliding sleeve were placed in the tubing across the Lewis Shale interval for testing. The packer and sliding sleeve have been removed as follows:

2/7/98

MIRU Big A #18. Closed sliding sleeve and set plug in "F" nipple. ND WH. Installed BPV and NU BOPs. Unseat packer and COOH w/packer and sliding sleeve. Circ. hole clean.

RIH w/2-3/8" tubing and landed @ 5826' with "F" nipple set @ 5795'. ND BOPs and NU WH. PT tubing. Pumped off check. RD & MO. Turned well over to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE Regulatory Assistant DATE 2-12-98

TYPE OR PRINT NAME Patsy Clugston TELEPHONE NO. 505-599-3454

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH

CONDITIONS OF APPROVAL, IF ANY:

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE FEB 25 1998