

District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Arcoia, NM 88211
District III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE
DEPUTY OIL & GAS INSPECTION
SEP 11 5 1995

PIT REMEDIATION AND CLOSURE REPORT

Operator: PHILLIPS PETROLEUM COMPANY Telephone: (505) 599-3460
Address: 5525 Hwy. 64, NBH 3004, Farmington, NM 87401
Facility Or: San Juan 29-5 Unit #24 (MW)
Well Name B
Location: Unit or Qtr/Qtr Sec NW NE Sec 17 T 29N R 6W County Rio Arriba
Pit Type: Separator X Dehydrator Other Condensate Tank
Land Type: BLM X, State , Fee , Other

Pit Location: Pit dimensions: length 22', width 22', depth 3-1/2'
(Attach diagram) Reference: wellhead X, other
Footage from reference: 85'
Direction from reference: 60 Degrees East North N
of
X West South

Depth To Ground Water: 55'
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)
Less than 50 feet (20 points)
X 50 feet to 99 feet (10 points)
Greater than 100 feet (0 Points) 10

Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)
RECEIVED
MAY - 9 1994
OIL CON. DIV.
DIST. 3
Yes (20 points)
No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)
Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
X Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: NA Dated Completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: NA

Initial assessment of pit showed soils to be clean

at the surface and at three feet below pit

bottom.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location Deepest part of pit. Sampled with
Closure Sampling: a backhoe.
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample depth 3' below pit bottom

Sample date 7/2/93 Sample time _____

Sample Results

Benzene(ppm) 0

Total BTEX(ppm) 0.169

Field headspace(ppm) 13.2

TPH 12

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 4/12/94

SIGNATURE Ed Haselv

PRINTED NAME Ed Haselv
AND TITLE Environmental Engineer

PIT NO	WELL NAME	U.S. T.R.	PIT TYPE	RANK SCORE	CLOSURE STAND/MD (PPH)	DATE 1993	GROUNDWATER SAMPLE NO	SOIL TYPE	PIT TYPE	SAMPLE NO	Organic Vapor Matter (PPM)	Recoverable Ptn, Hydro. (PPM)	Benzene	Toluene	Ethyl Benzene	Xylene	TOTAL BTEX	STATUS
PA001	SAN JUAN 29-6, #7A	E342906	STP/TANK	10	1000	6-29		SC	EARTHEN	T1-10	725	1940						REM
PA002	SAN JUAN 29-6, #7A	E342906	RE3/BLOW	10	1000	6-29		SC/SP	EARTHEN	T1-7	0							CLOSE
PA003	SAN JUAN 29-6, #95	L342906	SEP	10	1000	6-29		CL/SC	EARTHEN	T1-9	493	184	0	67	241	200	387.1	TEST
PA004	SAN JUAN 29-6, #52A	P342906	SEP	10	1000	6-29		CL/SC	EARTHEN	T1-10	419	380	640	39900	6200	59000	105740	REM
PA005	SAN JUAN 29-6, #48-35	A352906	SLP	20	100	6-29		CL/SP/SM	EARTHEN	T1-10.5	442							REM
PA006	SAN JUAN 29-6, #50	H362906	SLP	10	1000	6-30		SM/SC	EARTHEN	T1-14	581							TEST
PA007	SAN JUAN 29-6, #101	A362906	SEP	10	1000	6-30		SC/SM	EARTHEN	T1-8	58.3	740						CLOSE
PA008	SAN JUAN 29-5, #41-31	A312905	SEP	20	100	6-30		SM/SC	EARTHEN	T1-14	574							REM
PA009	SAN JUAN 29-5, #37-31	L312505	SEP	10	1000	7-01		CL/SC	EARTHEN	T1-8	516	57	0	3000	136	140.3	3276.3	CLOSE
PA010	SAN JUAN 29-5, #53	L322905	SEP	20	100	7-01		CH	EARTHEN	T1-4	1.9	18						CLOSE
PA011	SAN JUAN 29-5, #36	L332905	SEP	10	1000	7-01		CH	EARTHEN	T1-4	1.5	12						CLOSE
PA012	SAN JUAN 29-5, #89	K342905	SEP	20	100	7-01		SM	EARTHEN	T1-12	472	1200	87	235	3100	4230	7662	REM
PA013	SAN JUAN 29-5, #88	G342905	SLP	0	5000	7-01		SC/SM	EARTHEN	T1-10	447	1100	15.5	202	6800	7130	14147.5	TEST
PA014	SAN JUAN 29-5, #46-21	B212905	SEP	10	1000	7-02		CH/SC	EARTHEN	T1-4.5	0.9	0						CLOSE
PA015	SAN JUAN 29-5, #34-17	B172905	SEP	10	1000	7-02		CL/CH/SC	EARTHEN	T1-4	3.9	12	0	70	13.4	86	169.4	CLOSE
PA016	SAN JUAN 29-5, #20 MV	M072905	SLP	20	100	7-02		SC/SM	EARTHEN	T1-6.5	604	1350	940	59700	13600	102500	176740	REM
PA017	SAN JUAN 29-6, #10 MV	B022906	SEP	10	1000	7-06		CL/SM	EARTHEN	T1-5	652	1940	0	9200	4330	63800	77350	REM

SOIL TYPE: C - Clay, M - Silt, S - Sand, G - Gravel Plasticity: L - None, H - Plastic Grading: P - Poorly, B - Well