

NUMBER OF COPIES RECEIVED	
DISTRICT OFFICE	
SANITARI	
FILE	
U.S.A.T.	
LAND OFFICE	
TRANSPORTER	
OIL	
GAS	
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company El Paso Natural Gas Company		Address P.O. Box 990, Farmington, New Mexico	
Lease San Juan Unit 29-7	Well No. 4	Unit Letter N	Section 10
		Township 29 North	Range 7 West
Date Work Performed 3-29-63	Pool Blanco Mesa Verde	County Rio Arriba	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **See below:**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

This well is bridged in the Meneffee Section of the open hole.

3-29-63: The 2 3/8" O.D. EUE tubing was perforated above the bridge with the Kinley tubing perforation (1/4" diameter holes.) One (1) hole at (1082') and one (1) hole at (4731').



Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by	Original Signed By A. R. KENDRICK	Name	Ben Boyd
Title	PETROLEUM ENGINEER DIST. NO. 3	Position	Production Engineer
Date	APR 3 1963	Company	El Paso Natural Gas Company