Form 9-331 (May 1963)

16.

## UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 42-R142

LEASE	DESIGNATION	AND	SERIA
SF-C	78281		

5.

**GEOLOGICAL SURVEY** 

OI IL IDDI	LICTICEC	4 4 10	$DCD \triangle DTA$	$\sim$	
		$\Delta N = 1$	REPORTS	( )(\)	W/FIIC
JUNEAU JELI	LACTICE	$\sim$ 1317	INEL CARLO	1713	AA F F - 1 - 12

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

(Do not use this	form for proposals to drill or to deepen or plug back to a different res  Use "APPLICATION FOR PERMIT—" for such proposals.)	ervoir.
OIL GAS WELL	OTHER .	7. UNIT AGREEMENT NAME  San Juan 29-5 Unit
2. NAME OF OPERATOR	8. FARM OR LEASE NAME	
Northwest I	Pipeline Corporation	San Juan 29-5 Unit
P.O. Box 90		9. WELL NO. 72
4. LOCATION OF WELL ( See also space 17 be At surface	Report location clearly and in accordance with any State requirements.* ow.)	10. FIELD AND POOL, OR WILDCAT Basin Dakota
1835' FNL 8	11. SEC., T., R., M., OR BLK. AND BURVEY OR AREA	
		SEC 17, T29N,R5W NMPM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6600 GR	Rio Arriba New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT ALTERING CASING	_
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING ABANDONMENT*	_
REPAIR WELL		CHANGE PLANS		(Other) Temporarily Abandon X	
(Other)		٠		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	_

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- 2-1-75 Spud @ 5:00PM
- 2-2-75 Drill 13-3/4" hole to 294' KB Ran 6 jts (280') 9-5/8" 36# K-55 casing & set @ 294' KB. Cemented with 280 sacks. Cement circ. WOC 12 hours & test to 600 psi for 30 min. - Test OK.
- Drill 8-3/4" hole to 3870' KB Ran 94 jts (3855') 7" 20# K-55 csg & set @ 3869' KB Cemented w/165 sx WOC 12 hr - Test csg to 1000 psi for 30 min. - OK.. B&R Temp Survey - 2450'.
- 2-12-75 Gas drill 6-1/4" hole to 8025' KB. Log well Gamma Induction & Formation Density.
- 2-13-75 Ran 250 jts (8011') 4-1/2" 10.5# & 11.6# K-55 csg & set @ 8024' KB. Cemented with 320 sx. Top cement by temperature survey 3500'.
- 2-14-75 Clean out to float collar @ 8011. KB. Test casing to 4000 psi Spot acid & perforate 7820; to 8008' with 9 (0.34") holes - Breakdown w/acid & ball sealers. Start frac with 500 gal pad w/no sand & start sand @ 1/2 ppg. Inj. rate-19 BPM @ 3800 psi. One pump truck went out and sanded off with 16000# sand in formation.
- 2-15-75 Clean out to T.D. w/gas Well gauged 247 MCF w/heavy water. Bit stuck coming off bottom. Circ hole with water & free bit - tubing parted while coming out of hole-2236' fish in hole.
- 3-9-75 Fishing Csg collapsed- roll out Recovered 646' fish Could not recover remaining 1590' of fish - Fishing operations suspended @ 11:15 AM.
- 3-10-75 Well will be temporarily abandoned until a decision is reached to try and complete un hole or plug & abandon

18. I hereby certify that the foregoing is true and correct  SIGNED O.B. Whitenburg js	Production & Drilling Eng.	DATE March 13, 1975
(This space for Federal or State office use)  ATARCHE PROVED  CONDITIONS OF APROVAL, PANY:  MAR 1 1975	THE SO OF STREET	DATE
· · · · · · · · · · · · · · · · · · ·	e Instructions of Reference Side	