Form 9-331 (May 1963)

3.

16.

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

SUBMIT IN TRIPLICATES

Form approved, Budget Bureau No. 42 X1424. 5, LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

VRAIMP	NOTICES	AND	REPORTS	DM	VA/ELLC	
ろひいひたて	INCHICES.	AINU	REPURIS.	$\cup N$	- WELLS	

NM 03471 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Rio Arriba

NM

		In to drill or to deepen or plug back to a different reservoir, HON FOR PERMIT" for such proposals.)	
1,	CHL GAS X OTHER		7. UNIT AGREEMENT NAME San Juan 29-6 Unit
2.	Northwest Pipeline Co	rporation	8. FARM OR LEASE NAME San Jaun 29-6 Unit
3.	P.O. Box 90, Farmington	on, New Mexico 87401	9. WELL NO. 47A
4.	LOCATION OF WILL (Report location cle See also space 17 below.) At surface 820 * FSL & 1	arly and in accordance with any State requirements.* 730 FEL	10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 28, T29N, R6W
14	PERMIT NO.	15. ELEVATIONS (Show whether DF, ET, GE, etc.)	12. COUNTY OR PARISH 13. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

6372' GR

BOTTON OF INTENTION TO.			SUBSEQUENT REPGRT OF:				
	1			ĺ			·
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OF ACIDIZING		ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)			
(Other)				(Note: Report resu Completion or Reco	ilts of multiple mpletion Repor	e completion on Wel t and Log form,)	i

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-11-76 MOL & RU. Spud at 7:30 PM. Drilled 12 1/4" hole to 225'.

12-12-76 Ran 5 jts. (201') 9 5/8", 36#, K-55 casing set at 213' KB. Cemented with 115 sks. C1. "B" w/ 1/4# Flocele /sk. & 3% CC. Cement circulated. WOC 12 hrs. Pressure tested casing to 600 PSI for 30 min., held OK.



DEC 14 1976

U. S. GEOLOGICAL SURVEY DURANGO, COLO.

8. I hereby certify that the foregoing is true and correct SIGNED		DATE12/13/76
(This space for Federal or State office use)		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE .	DATE

*See Instructions on Koverse Side