UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Office Instructions on respected) 5.

Form approved. Budget Burean No. 42-Ri					
 DESIGN.					

GEOLOGIC

AL SURVEY	NM 03040-A
D REPORTS TO THE WELLS WELL	6. IF INDIAN, ALLOTTEE OR TRIBE NAME

(Do-u	SUNDRY NO of use this form for pro- Use "APPI	OTICES AND REPO operate to defil or to deepen of CATION FOR PERMITS OF	ORTS PICE WE or plus Proposals.)	Er North	U. IF INDIAN, ALLOSTIE OR TRIBE NAME
OIL WELL .	GAS X OTHE	?	DEC	1 4 1976	7. UNIT AGREEMENT NAME San Juan 29-6 Unit
	west Pipeline	Corporation	II S GFOLO	GICAL SURVEY	San Juan 29-6 Unit
3, ADDRESS O			DURAN	GO, COLO.	9. WELL NO.
4. LOCATION	or well (Report location page 17 below.)	on clearly and in accordance	87401 with any State requi	rements.*	46A 10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde
	940' FNL &	790' FWL			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO).	15. ELEVATIONS (Show v	whether DF, RT, GR, etc.)	Sec. 27, T29N, R6W 12. COUNTY OR PARISH 13. STATE
		6383	GR GR	····	Rio Arriba NM
16.	Check	Appropriate Box To Inc	dicate Nature of I	Notice, Report, or	Other Data
	NOTICE OF IN		1		EQUENT REPORT OF:
TEST WAT	TER SHUT-OFF	PULL OR ALTER CASING	WAT	TER SHUT-OFF	REPAIRING WELL
PRACTURE		MULTIPLE COMPLETE	FRAC	CTURE TREATMENT	X ALTERING CASING
SHOOT OR REPAIR W		ABANDON* CHANGE PLANS		her)	X ABANDONMENT*
(Other)				(Nome . Report room	lts of multiple completion on Well npletion Report and Log form.)
	ROPOSED OR COMPLETED of work. If well is directly this work.) *	OPERATIONS (Clearly state all ctionally drilled, give subsur	pertinent details, a face locations and m		es, including estimated date of starting any ical depths for all markers and zones perti-
11-26-76	9 5/8", 36#,	oud at 3:00 PM. K-55, ST & C cas Le per sk. and 3%	ing set at 2	19 $^{\circ}$. Cemente	220'. Ran 5 jts. (206') ed with 115 sks. Cl. "B"
11-27-76	Pressure test	ed casing to 600	PSI, held 0	K.	
12-1-76	Drilled 8 3/4 set at 3660'.	Cemented w/100	w/mud。 Ran sks. 65/35	97 jts. (3647 poz w/12% ge1	7') 7", 20#, K-55 casing , followed by 50 sks
12-2-76	Top of cement held OK.	: at 2400° by tem	p. survey. I	Pressure test	ed 7" casing to 600 PSI,
12-4-76	Ran 66 jts. ((2158') 4 1/2", 13 at 5638'. Cement	1.6# , K−55 ca	asing liner s	duction & Density Logs. et from 3514' to 5672'. w/4% gel & 1/4 cu.ft.
12-5-76	Cleaned out 4	1/2" to 5638".	Tested wtih	3500 PSI, wo	uld not hold.
IQ Though-	Mid One Co				
SIGNED D	that the foregoing	(1)	m Production	n Engineer	DATE12/13/76
	for Federal or State of				
APPROVEI CONDITION	O BY NS OF APPROVAL, IF	TITI	JE	beult	DATE
		*See last	ructions on Rayan	OIL COM	Com j