

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM 012698

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME San Juan 29-6 Unit
2. NAME OF OPERATOR Northwest Pipeline Corporation	8. FARM OR LEASE NAME San Juan 29-6 Unit
3. ADDRESS OF OPERATOR PO Box 90, Farmington, New Mexico 87401	9. WELL NO. 110
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1810' FNL & 1000' FEL	10. FIELD AND POOL, OR WILDCAT Blanco Pictured Cliffs
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1 T29N R6W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6514' GR	12. COUNTY OR PARISH Rio Arriba
	13. STATE N.M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐"Summary" ☒

(NOTE: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-24-77 Spud 12 1/4" surface hole. Ran 8 5/8" csg set @ 124' KB. Cmt w/ 85 sks.  
Circ 4 bbls.

9-3-77 Drlg 6 3/4" hole. TFB #2.

9-9-77 Ran 2 7/8" tbg to 3659'. Cmtd w/ 170 sks. Tested csg to 4000 psi for 15 min.  
Top of cmt by temp survey 2525'.

9-10-77 Rig released.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

*Barbara E. Rex*

TITLE

Production Clerk

DATE 9-16-77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

SEP 19 1977

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY  
BIRMINGHAM, ALA.