

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR
Northwest Pipeline Corporation

3. ADDRESS OF OPERATOR
PO Box 90, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 860' FNL & 1140' FWL
AT TOP PROD. INTERVAL: Same Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>

(other) "Drilling & Completion Summary"

5. LEASE
SF 080379

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
San Juan 29-6 Unit

8. FARM OR LEASE NAME
San Juan 29-6 Unit

9. WELL NO.
20A

10. FIELD OR WILDCAT NAME
Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 8 T29N R6W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6804' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-18 to 21, 1978 Drilling
9-21-78 Reached depth of 4010'. Ran 7", 20#, K-55, ST&C csq set @ 4010'. Cmted w/ 150 sks. Plug down @ 1345 hrs. WOC. Top of cmt by temp survey @ 2700'. Tested csq to 1200 psi, held OK.
9-22-78 Drilling.
9-23-78 Ran 4-1/2" liner set from 3862' to 6065'. Cmted w/ 210 sks C1"C w/ 4% gel. Plug down @ 0830 hrs. WOC.
9-24-78 Pressure tested csq & liner to 3500 psi for 30 min, held OK. Ran GR-Neutron log & perfed 30 holes from 5552' to 6000'. Pumped 1000 gal acid & dropped 50 balls. Fraced w/ 79,870# 20/40 sand in slick wtr. MIR 67 BPM, AIR 48 BPM, MIP 2000 psi, AIP 1100 psi. ISIP = 0. Job complete @ 2230 hrs.
9-26-78 Gauged well @ 2863 MCFD thru annulus. Landed 2-3/8" tbq @ 5961'. Rig released @ 0600 hrs. SI for test.
Subsurface Safety Valve: Make and Type Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Barbara C. Rex TITLE Production Clerk DATE September 29, 1978

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: