UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM-18325
SUNDRY NOTICES AND REPORTS ON WELL (Do not use this form for proposals to drill or to deepen or plug back to a di reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Schalk 29-4
1. oil gas XX other	9. WELL NO. + 7
2. NAME OF OPERATOR JOHN E. SCHALK	TO MED OR WILLIAM NAME
3. ADDRESS OF OPERATOR P. O. BOX 25825 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1740' FSL, 1560' FWL, Sec.26, AT SURFACE: Township 29North, Range4W	Sec. 26, T-29N, R-4W
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NO REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7060' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Drilling X 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clean including estimated date of starting any proposed work. If we have to starting any proposed work.	(NOTE: Report results of multiple completion or zone change on Form 9–330.) rly state all pertinent details, and give pertinent dates, well is directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones	pertinent to this work.)
•	sing @ 266' KBM. Cemented with
Subsurface Safety Valve: Manu. and Type	MAY 23 1979 MAY 2011. 3
18 (Lherany certify that the foregoing is true and correct	

MAY 22 1979

(This space for Federal or State office use)

TITLE .