UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**


1	5. LEASE
ļ	NM-10431
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
_	
	7. UNIT AGREEMENT NAME
nt	
	8. FARM OR LEASE NAME
	Burns Ranch
	9. WELL NO.
	#1
	10. FIELD OR WILDCAT NAME
	Campo Gallup
	11. SEC., T., R., M., OR BLK. AND SURVEY OR
.7	Section 13, T29N, R4W
	12. COUNTY OR PARISH 13. STATE
	Rio Arriba New Mexico
	14. API NO
<u>Е</u> ,	
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	(NOTE: Report results of multiple completion or zone
	change on Form 9-330.)

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differe reservoir. Use Form 9–331–C for such proposals.) 1. oil gas other well well 2. NAME OF OPERATOR Southland Royalty Company 3. ADDRESS OF OPERATOR Drawer 570, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 AT SURFACE: 790' FNL & 790' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES Perforation and Stimulation ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perforated Gallup at 7301', 7308', 7315', 7322', 7386', 7393', 7400', 7407', 7414', 7421', 7428', 7235'. Total of 12 holes.

Fraced with 14,500 gallons of water and 4,500# of 20/40 sand.



Subsurface Safety Valve: Manu. and Type ___ 18. I hereby certify that the foregoing is true and correct _____ TITLE District Engineer DATE _ (This space for Federal or State office use) DATE

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: