

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-039-25481

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
5525 Highway 64, NBU 3004, Farmington, NM 87401

7. Lease Name or Unit Agreement Name

San Juan 29-5 Unit

8. Well No.
San Juan 29-5 Unit #53M

9. Pool name or Wildcat
Basin Dakota & Blnco MV

4. Well Location
Unit Letter 0 : 978' Feet From The South Line and 1611' Feet From The East Line

Section 32 Township 29N Range 5W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6500'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Spud Report ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-1-95

MIRU Big A #23 to drill well. Spudded 14-3/4" surface hole @ 2030 hrs on 7/1/95. Drilled to 370'. CO. RIH w/10-3/4" 45.5# J-55 8rd ST&C casing and set @ 367'. RU Dowell to cement. Pumped 20 bbls water. Mixed and pumped 300 sx Class G w/1/4#/sx cellophane & 3% CaCl2. Yield 1.15 @ 15.8 ppg. Rate 3.7 bpm @ 80 to 120 psi. Displaced w/35.5 bbls water @ 3.5 bpm 100 psi. Circ. 8 bbls cement to surface. Wood plug down @ 10:56 am on 7-2-95. WOC 4 hours. NU WH & BOPs. Pressure tested. Good test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Louis E. Robinson TITLE Sr. Drilling Engineer DATE 7-5-95

TYPE OR PRINT NAME LOUIS E. ROBINSON TELEPHONE NO. 599-3415

(This space for State Use)

Original Signed by FRANK T. CHAVEZ

APPROVED BY _____ TITLE SUPERVISOR DISTRICT #3 DATE JUL - 7 1995

CONDITIONS OF APPROVAL, IF ANY: