



30-039-26444

**Key Energy Services, Inc.**

Four Corners Division  
5851 US Highway 64  
P.O. Box 900  
Farmington, NM 87499

Phone: 505-327-4935  
Fax: 505-327-4962

January 02, 2001

Rig No. 47

Phillips Petroleum Company  
5525 Hwy 64 NBU 3004  
Farmington, NM 87401

Attn: Patsy Clugston



This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 29-6 #18R well in S05-T29N-R06W, in Rio Arriba, county, New Mexico.

| Depth | Deviation             | Depth | Deviation              |
|-------|-----------------------|-------|------------------------|
| 154'  | $\frac{1}{2}^{\circ}$ | 3408' | $\frac{1}{2}^{\circ}$  |
| 306'  | $1^{\circ}$           | 4118' | $1^{\circ}$            |
| 826'  | $\frac{1}{4}^{\circ}$ | 4421' | $1^{\circ}$            |
| 1323' | $\frac{1}{2}^{\circ}$ | 4951' | $1\frac{1}{4}^{\circ}$ |
| 1822' | $1^{\circ}$           | 5448' | $\frac{3}{4}^{\circ}$  |
| 2326' | $\frac{3}{4}^{\circ}$ | 5946' | $\frac{3}{4}^{\circ}$  |
| 2882' | $\frac{3}{4}^{\circ}$ | 6286' | $\frac{3}{4}^{\circ}$  |

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith  
Drilling contract manager

  
Notary Public

My commission expires:

6/26/02