

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

August 21, 2002

Dolores Silseth Burlington Res O&G Co PO Box 4289 Farmington NM 87499

07544

Re: San Juan 29-7 Unit 53, H-27-29N-07W, API # 30-039-08544

Dear Dolores:

The 2002 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before October 20, 2002.

Reference RBDMS CTP0223256085 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin

Deputy Oil & Gas Inspector

Charlie T. L. nrin

cperrin@state.nm.us

CTP/mk

CC: Well file

CP