



(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. 078379
Unit San Juan 29-7
14-01-001-567

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>	☒

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 65 is located 990 ft. from [N] line and 1800 ft. from [E] line of sec. 22
[S]
NE Sec. 22 23N 7E N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco Mo Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6723 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-20-58 Total Length 5964'. Clean out 5088'. Water fractured Joint Lookout perforated intervals 5760-5772, 5782-5796, 5818-5837, 5874-5884 with 60,480 gal. water and 60,000# sand. BT pr. 2450#, Max. pr. 2450#, avg. tr. pr. 1150, 1250, 1300, 1425, 1550#. Injection rate 70 BPM. Flush 9660 gal. Dropped 2 sets of 13 balls for 4 stages.

2-20-58 Temporary bridge plug at 5650'. Water fractured Cliff House perforated intervals 5344-5354, 5379-5386, 5405-5414, with 37,800 gal. water and 40,000# sand. BT pr. 2400#, Max. pr. 2400#, avg. tr. pr. 1500, 1400, 1500#. Injection rate 77 BPM. Flush 9940 gal. Dropped 2 sets of 17 balls for 3 stages.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

RECEIVED
MAR 1 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO
By ORIGINAL SIGNED E.E. McNALLY
Title Petroleum Engineer.