

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe
Lease No. 078502
Unit W $\frac{1}{2}$ Sec. 11

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 19 1963

Vanderwart
Well No. 1-11 is located 1474 ft. from XXX line and 1728 ft. from XXX line of sec. 11
SW $\frac{1}{4}$ Sec. 11 T29N R8W N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the ~~derrick floor~~ XXXXXXXXXXXXXXXXXXXXXXXXXXXX above sea level is 6302 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 165' with 5 jts. of 10-3/4" casing landed @ 157'.

A steel plate was welded in top of surface casing. Well marker installed and surface leveled.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Box 1198

Farmington, New Mexico

Original signed by

A. R. Gibson

By

A. R. Gibson

Title

Dist. Supt.