

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.  
SF 078416-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input checked="" type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR El Paso Natural Gas Company			8. FARM OR LEASE NAME Hardie
3. ADDRESS OF OPERATOR PO Box 990, Farmington, NM 87401			9. WELL NO. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990'S, 990'E			10. FIELD AND POOL, OR WILDCAT Undes. Pictured Cliffs
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6294'GL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T-29-N, R-8-W NMPM
16.		12. COUNTY OR PARISH San Juan	13. STATE New Mexico

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO :

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)


FULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON\*  
CHANGE PLANS


## SUBSEQUENT REPORT OF :

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)


<input checked="" type="checkbox"/>

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*



(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7-24-72 Spudded well. Drilled surface hole. Ran 4 joints 8 5/8", 24#, K-55 surface casing, 129' set at 142'. Cemented with 107 cu. ft., circulated to surface. WOC 12 hours, held 600#/30 minutes.



18. I hereby certify that the foregoing is true and correct

SIGNED  TITLE Petroleum Engineer DATE July 25, 1972

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: