

## BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|                                                                                                                                                                     |  |                                                                    |                 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------------------------|-----------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER                                                                             |  | 5. LEASE DESIGNATION AND SERIAL NO.<br>SF-078487                   |                 |
| 2. NAME OF OPERATOR<br>McKenzie Methane Corporation                                                                                                                 |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                               |                 |
| 3. ADDRESS OF OPERATOR<br>1911 Main Ave., #255, Durango, Colorado 81301                                                                                             |  | 7. UNIT AGREEMENT NAME                                             |                 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><br>1065' FNL, 1765' FEL |  | 8. FARM OR LEASE NAME<br>Roelofs 10 B                              |                 |
| 14. PERMIT NO.<br>API 30-045-28594                                                                                                                                  |  | 9. WELL NO.<br>#11                                                 |                 |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>6296' GR                                                                                                          |  | 10. FIELD AND POOL, OR WILDCAT<br>Basin FT Coal                    |                 |
|                                                                                                                                                                     |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec10-T29N-R8W |                 |
|                                                                                                                                                                     |  | 12. COUNTY OR PARISH<br>San Juan                                   | 13. STATE<br>NM |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

|                                              |                                               |
|----------------------------------------------|-----------------------------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETE <input type="checkbox"/>    |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input type="checkbox"/>             |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         |
| (Other) <input type="checkbox"/>             |                                               |

## SUBSEQUENT REPORT OF:

|                                                             |                                          |
|-------------------------------------------------------------|------------------------------------------|
| WATER SHUT-OFF <input type="checkbox"/>                     | REPAIRING WELL <input type="checkbox"/>  |
| FRACTURE TREATMENT <input type="checkbox"/>                 | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/>              | ABANDONMENT* <input type="checkbox"/>    |
| (Other) <input checked="" type="checkbox"/> Drilling Report |                                          |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

SEE ATTACHED

**RECEIVED**  
OCT 29 1991  
OIL CON. DIV. 1  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

*RJ Sagle / C.S.*

TITLE Operations Manager

DATE 10-1-91

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

**ACCEPTED FOR RECORD**

OCT 24 1991

\*See Instructions on Reverse Side

NMCD

FARMINGTON RESOURCE AREA

BY

McKENZIE METHANE CORPORATION  
DAILY DRILLING REPORT  
Durango Office

9-27-91      Roelofs 10 B #11  
              Sec10-T29N-R8W, San Juan Co., NM  
              AART: Drlg cmt.                      DEPTH: 271'  
              DAILY: MIRU 4 Corners Drilling #7. Spud @ 12:45 PM  
              9-26-91. Drlg rat & mouse hole & 271' of 12-1/4 surf  
              hole. Circ & cond hole, TOH w/ drlg assembly. Ran 6  
              jts. of 8-5/8, 24#, J55 STC surf csg set @ 269' KB.  
              RU Cementers Inc., cmt w/ 250 sx Class B (295 cu ft)  
              w/ 2% CaCl. Circ 14 bbl cmt to surf. PD & holding @  
              9:30 PM 9-26-91. WOC. NU. PT stack to 600 PSI (no  
              leaks). TIH. Start drlg cmt.  
              MUD: spud                      Surveys: 95' -3/4, 246' -3/4.

9-28-91      Roelofs 10 B #11  
              Sec10-T29N-R8W, San Juan Co., NM  
              AART: Drlg                      DEPTH: 2233'  
              DAILY: Drlg out under surf, from 271'-2233'. Taking  
              500' surveys. Presently drlg 45 FPH. Drlg sand & shale.  
              MUD: fresh H2O                      Surveys: 436' -1, 773' -3/4,  
              1274' -3/4, 1808' -1/2.

9-29-91      Roelofs 10 B #11  
              Sec10-T29N-R8W, San Juan Co., NM  
              AART: Drlg                      DEPTH: 3046'  
              DAILY: Drlg from 2233' -3046'. Taking 500' surveys,  
              presently drlg 45 FPH. Drlg top of PC.  
              MW: 9.1              Vis: 36              Surveys: 2311' -1,  
              2811' -2.

9-30-91      Roelofs 10 B #11  
              Sec10-T29N-R8W, San Juan Co., NM  
              AART: WOC                      DEPTH: 3085'  
              DAILY: Drlg 3046'-3085'. TD reached @ 7:15 AM 9-29-91.  
              Short tripped 10 stands, circ & cond hole, TOH w/ drlg  
              assembly. RU Schlumberger & ran open hole logs, first  
              log on bottom @ 11:45 AM. RD. TIH. Circ & cond, LDDP &  
              DC. RU P.T.I. & ran 77 jts of 4-1/2, J55, 11.6 8RD LTC  
              csg. landed @ 3078 KB. RD casers, RU Dowell & cmt w/  
              500 sx 65/35 POZ, 6% gel, 1/4#/sx cellophane for lead &  
              150 sx 50/50 POZ, 2% gel & 1/4#/sx cello. proceeded by  
              20 bbl mud flush. Circ 3/4 bbl cmt to surf. PD & hold-  
              ing @ 11:15 PM, RR @ 2:30 AM 9-30-91.  
              MW: 9.0              Vis: 36              Surveys: 3045' -1-1/2