

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
TO OTHER INSTRUCTIONS ON REVERSE SIDEForm approved
Budget Bureau No. 42 E1421
5. LEASE DESIGNATION AND SERIAL NO.

SF-078201

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Florance

9. WELL NO.

61

10. FIELD AND POOL, OR WILDCAT

Blanco P.C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12, T29N, R9W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1. WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

1860 Lincoln St., Suite 1200, Denver, Colo. 80295

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1120' FNL and 880' FEL, Unit A

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6279' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☒ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Re-completion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

8/1 - 8/ /77 MIRUPU. Found casing leak between 1460' - 1490'. Squeezed with 35 sacks of Class B Cement. Drilled out cement. Found casing leak between 1430' - 1490'. Squeezed with 25 sacks of Class B Cement. Still had casing leak. Status = Temporarily Abandoned with sand and Cal - seal plug above perfs. Top of plug = 2870'. Expense of casing repair exceeds revenues at this time.



18. I hereby certify that the foregoing is true and correct

SIGNED

A. A. Myers

TITLE Div. Production Manager

DATE

8-10-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

AUG 16 1977

U. S. GEOLOGICAL