


District I
P.O. Box 1990, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
1000 Rio Grande Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE



(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: CONOCO INC. Telephone: 505-324-5813

Address: 3315 Bloomfield HWY. FARMINGTON N.M. 87401

Facility Or: State Com 39
Well Name

Location: Unit or qtr/qtr sec C sec 36 T29N R8W county SAN JUAN

Pit Type: separator ___ Dehydrator ___ other TANK DRAIN PIT

Land Type: BLM ___ State ☒ Fee ___ Other ___

Pit Location: Pit dimensions: length 24', width 21', depth 4'
(Attach diagram)

Reference: wellhead ☒, other ___

Footage from reference: 18'

Direction from reference: 244 Degrees ___ East North ___
☒ West South ___

Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)

Less than 50 feet	(20 points)
50 feet to 99 feet	(10 points)
Greater than 100 feet	(0 points) <u>0</u>

Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)

Yes	(20 points)
No	(0 points) <u>0</u>

Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)

Less than 200 feet	(20 points)
200 feet to 1000 feet	(10 points)
Greater than 1000 feet	(0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 8-24-99 Date Completed: 8-24-99

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description Of Remedial Action: SAMPLE TAKEN, T.II Bottom of
Pit 1' IN. Hit Bed Rock 1' IN - BACK Fill clean SOIL

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit:

Sample location Center of Pit

Closure Sampling:

(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 2'

Sample date 8-16-99 Sample time 1324

Sample Results

Benzene (ppm) .235

Total BTEX (ppm) 6.970

Field headspace (ppm) 255

TPH 34230

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEF

DATE 12-2-99

SIGNATURE

Judson Valdez

PRINTED NAME
AND TITLE

Judson Valdez P.L.

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	707003-087
Sample ID:	TDP - Grab	Date Reported:	08-24-99
Laboratory Number:	F959	Date Sampled:	08-16-99
Chain of Custody No:	7109	Date Received:	08-20-99
Sample Matrix:	Soil	Date Extracted:	08-23-99
Preservative:	Cool	Date Analyzed:	08-23-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	2,130	0.2
Diesel Range (C10 - C28)	32,100	0.1
Total Petroleum Hydrocarbons	34,230	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **State Com 39. OVM Reading 255.
Hit Rock Bed 1' In.**


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco	Project #:	707003-087
Sample ID:	TDP - Grab	Date Reported:	08-24-99
Laboratory Number:	F959	Date Sampled:	08-16-99
Chain of Custody:	7109	Date Received:	08-20-99
Sample Matrix:	Soil	Date Analyzed:	08-23-99
Preservative:	Cool	Date Extracted:	08-23-99
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	235	8.8
Toluene	196	8.4
Ethylbenzene	475	7.6
p,m-Xylene	4,600	10.8
o-Xylene	1,460	5.2
Total BTEX	6,970	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	100 %
	Bromofluorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: State Com 39. OVM Reading 255.
Hit Rock Bed 1' In.


Analyst



Review

7109

[illegible]

Lease Name: STATE Com #39 FT/PC Operator: David Brind Date: 8-16-99

Site Security
(Indicate North)



Lease Name: State Com 39

Federal/ Indian Lease No: ST B 1118348

CA No.: NA

Unit: C

Legal Description: Sect: #6 TP: 29N R: 8W

County: San Juan, NM

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM