

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078740

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

San Juan 30-5 Unit

8. FARM OR LEASE NAME

San Juan 30-5 Unit

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREASec. 30, T-30-N, R-5-W  
N.M.P.M.

12. COUNTY OR PARISH

13. STATE

Rio Arriba

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER2. NAME OF OPERATOR  
El Paso Natural Gas Company3. ADDRESS OF OPERATOR  
Box 990, Farmington, New Mexico4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface990' N, 900' E  
990

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6229' GL

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

Plug and Abandonment

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Subject well has been plugged and abandoned in the following manner:

Spotted 75 sacks of cement over the perforations.

Cut off 5" casing at 3686', spotted a 50 sack cement plug over the casing stub.

Cut off 7" casing at 660', spotted a 100 sack cement plug over the casing stub.

Spotted a 25 sack cement plug over the base of the surface casing shoe at 270'.


Spotted a 25 sack cement plug at the surface.

Installed Plug and Abandonment marker. P &amp; A complete on 3-22-72.

Note: Another subsequent report will be submitted after location has been cleaned and leveled.

RECEIVED

APR 6 1972

U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE Petroleum Engineer

DATE April 4, 1972

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side