

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1421.
5. LEASE DESIGNATION AND SERIAL NO.

SF 079487-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 667'N, 833'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7512'GL

7. UNIT AGREEMENT NAME

San Juan 30-4 Unit

8. FARM OR LEASE NAME

San Juan 30-4 Unit

9. WELL NO.

2 (P&A)

10. FIELD AND POOL, OR WILDCAT

East Blanco Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19, T-30-N, R-4-W
NMPM

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well has been plugged and abandoned in the following manner:

11-9-71 Spotted a 50 sk. cement plug from 4300' to 4000'.

11-10-71 Perforated 4 squeeze holes at 3813'. Spotted a 50 sk. cement plug at 3813', and pressure displaced 25 sks. to cover Ojo Alamo outside casing and left 25 sks. inside casing to cover the Ojo Alamo.

11-12-71 Did not recover any 7" casing, pumped a 75 sks. cement plug down the 7" - 9 5/8" annulus. Placed a 15 sks. cement plug at the surface with a Plugged & Abandoned marker. Clean location.



RECEIVED

JAN 27 1972

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed W. D. Dawson

TITLE Petroleum Engineer

DATE January 25, 1972

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side